

Urgent Field Safety Notice

Commercial name of the affected product: Aptio Automation

FSCA-identifier: FSCA – AP2 – 201808 – 03

FSN-identifier: FSN – AP2 – 201808

Date: August, 2018

At the kind attention of:
To whom it may concern

Details on affected devices:

The following Automation System modules can be impacted by the issue:

Module	Part Number	
	Current module PN	Previous module PN (also impacted by the issue)
Input/Output Module	FLX-201	510; 509; F3.6-001
Storage Retrieve Module	FLX-207 and FLX-230	617; 517; F3.6-007 and F3.6-030
Rack Input Module	FLX-214	523; F3.6-014
Rack Output Module	FLX-216	F3.6-016
BNII Interface Module	FLX-287	n.a.
AU5800 Interface Module	FLX-275	n.a.
Sapphire Interface Module	FLX-264	n.a.
XN-9000 Interface Module	FLX-263 and FLX-290	n.a.

Table 1

According to our records in your facility at least one of these modules is present.

Description of the problem:

In the modules listed in Table 1, the transport mechanism that moves the robot along the axes generates a magnetic field which may interfere with pacemaker functionality at close distances.

The pacemaker safety label shown below is applied on the modules cover to warn who have a pacemaker about the risk in case they operate on these modules.



The information regarding the label included in the Operations Manual has been updated to specify that:

- the risk of a pacemaker malfunction applies to anyone with a pacemaker who may work on these modules;
- the minimum safety distance has been increased to 200 mm (7.87") from the transport mechanisms. Any person with a pacemaker must not get closer than this distance from the modules axes.

Refer to the attached OM Errata Corrige for the updated instructions.

Risk to Health:

Exposure to an electromagnetic field may interfere with pacemaker device functionality potentially leading to asynchronous pacing. Normal function typically resumes once the pacemaker is removed from the electromagnetic field. Symptomology related to electromagnetic interference may include palpitations, syncope, and/or difficulty breathing. Persons with pacemakers are generally aware of the potential adverse effects of magnetic fields and have been educated to avoid leaning on or near any potential source of electromagnetic interference.

Advise on action to be taken by the user:

1. Please be aware that personnel fitted with a pacemaker must not handle or work on these modules at distances lower than 200 mm.
2. Please review the attached OM Errata Corrige and save it with the Operations Manual you currently have available for future references regarding the "safety distance" required for pacemakers.

In addition:

- complete and return the Field Safety Notice Receipt Confirmation form attached to this letter within 15 days directly to Inpeco or to Inpeco representative.
- Please transfer this notice to whom it might concern.

Contact reference person:

For any clarification you may need, do not hesitate to contact:
Giorgia Amabile - Quality & Regulatory Manager
E-mail: Regulatory.Affairs@inpeco.com
Phone: (+41) 91 9118 258



We apologize for the inconvenience this situation may cause. Thank you for your cooperation. The undersign confirms that this notice has been/will be notified the appropriate Regulatory Agency.
Kind regards,



Georgia Amabile - Quality & Regulatory Manager



**FIELD SAFETY NOTICE RECEIPT CONFIRMATION and IMPLEMENTATION CHECK
Pacemaker Label**

FSN-identifier: FSN - AP2 - 201808

This response form is to confirm receipt of the enclosed Field Safety Notice dated August, 2018 regarding Pacemaker Label.

Please read each question and indicate the appropriate answer.

1. I have read and understood the Urgent Field Safety Notice instructions provided in this letter.
 YES NO

2. I have applied all the actions required in in this letter.
 YES NO

Please fill in the form and send a scan copy to Regulatory.Affairs@inpeco.com or to Inpeco representatives email address.

Name of person filling in the form:

Title:

Institution:

Automation Serial Number:

Street:

City:

State:


Phone:

Country:

Signature

Errata Sheet

This document amends the Operations Manual.

Icon	Description
	<p>This symbol indicates that the area access can cause risks to persons wearing a pace-maker.</p> <p>Any person with a pace-maker must keep a safety distance of at least 200 mm from the module axes.</p>

