

## **Urgent Field Safety Notice**

## Commercial name of the affected product,

3D Optical Coherence Tomography DRI OCT Triton / DRI OCT Triton plus (plus is a catalogue number)

#### **FSCA-identifier:**

GVP-2018-Triton-001

## Type of action

device modification

Date: 10 January 2018

Attention: Users of these devices

#### Details on affected devices:

Type of device: 3D Optical Coherence Tomography

Model number: DRI OCT Triton / DRI OCT Triton plus (plus is a catalogue number)

Serial number(s): Please see the Attachment 1

#### Description of the problem:

We have been aware following defect of "3D Optical Coherence Tomography DRI OCT Triton / DRI OCT Triton plus". As the result of phenomenon confirmation and investigation of the cause, we found that this phenomenon occurs according to the bug of embedded Firmware Ver. 1.13. We will do the correction of this defect by the software upgrade as voluntary field correction.

We apologize for any inconvenience this product update may cause you. Our goal is to ensure that your instrument continues to be as reliable as possible.

#### Phenomenon:

Under the firmware version 1.13, when the device is in a power save state, the Left & Right eye information based on the Main unit's position is stored in the device data. A software bug can arise when moving the Main unit to the opposite position in the power save state. When a new image is taken after cancelling the power save state, the device



has been observed to display the Left & Right eye information from the previous image instead of the new image, therefore providing inaccurate Left & Right eye information.

## Advise on steps to be taken by the user:

- 1. Check the Triton Serial number with the list in Attachment 1 of this FSN.
- 2. If there is a Serial number match; check embedded firmware version of this Triton.

  This firmware version is shown at the start-up screen of the Triton.
- 3. If this embedded firmware version is version 1.13; Ensure that the power save mode is switched off:
  - a. Go into the Triton setting menu.
  - b. Go to page 4
  - c. Set the value of "power save time" to "0 minutes"
  - d. Please keep "power save time" to "0 minutes" to keep the power save mode switched off until following steps will be taken by a certified Service engineer.

### Advise on steps to be taken by a certified Service engineer:

- 1. Check the Triton Serial number with the list in Attachment 1 of this FSN.
- 2. If there is a Serial number match; be sure to complete the following:
  - a. If the embedded firmware version of the Triton is version 1.13; Upgrade the Triton to firmware version 1.14
  - b. Check all effected Triton data by using the tool, provided by the manufacturer.
  - c. Send Closing Sheet, layout shown in Attachment 2 of this FSN, together with the log file to mentioned contact persons.

#### Contact reference person:

Takao Sugawara

TOPCON CORPORATION

75-1 Hasunuma-cho, Itabashi-ku, Tokyo, 174-8580, Japan

Phone: +81-3-3558-2618

FAX: +81-3-3966-5135



e-mail: t.sugawara@topcon.co.jp

Ivonne Breestraat

Topcon Europe Medical B.V

Essebaan 11, Capelle aan den Ijssel, 2908 LJ, The Netherlands

orenche

Phone: +31-10-4585077

FAX: +31-10-2844940

e-mail: <a href="mailto:lvonne.Breestraat@topcon.eu">lvonne.Breestraat@topcon.eu</a>

Sincerely yours,

Tadahiko Horiuchi

Senior Manager

**Quality Assurance Department** 

Quality Assurance Division

**TOPCON CORPORATION** 



## Attachment 1 of FSN GVP-2018-Triton-001

```
3D Optical Coherence Tomography DRI OCT Triton
101029, 107057, 107091, 107118, 107129, 107137, 107142
307001, 307003, 307004, 307010, 307028, 307046, 307050, 307062, 307065, 307072, 307073
980002, 980011, 980014, 980015, 980016, 980017, 980018, 980021, 980029, 980030, 980039,
980047, 980062, 980076, 980080, 980082, 980091, 980092, 980122, 980135, 980230, 980235,
980293, 980294, 980297, 980330, 980330, 980369, 980375, 980384, 980386, 980401, 980454,
980476, 980477, 980478, 980503, 980514, 980527, 980529, 980576, 980592, 980605, 980611,
980622, 980630, 980634, 980638

3D Optical Coherence Tomography DRI OCT Triton plus
```

3D Optical Coherence Tomography DRI OCT Triton plus
201009, 207062, 207063, 207065, 207066, 207068, 207078, 207093, 207113, 207114
801084, 801257, 807002, 807009, 807011, 807029
990004, 990009, 990010, 990024, 990036, 990046, 990065, 990077, 990080, 990083, 990084, 990102, 990118, 990119, 990122, 990128, 990134, 990136, 990137, 990140, 990141, 990142, 990143, 990177, 990196, 990203, 990210, 990218, 990225, 990250, 990254, 990268, 990273, 990277, 990290, 990293, 990306, 990309, 990329, 990334, 990335, 990338, 990343, 990347, 990356, 990366, 990369, 990372, 990375, 990381, 990396, 990400, 990404, 990419, 990427, 990420, 990440, 990443, 990477, 990480, 990482, 990483, 990488, 990494, 990498, 990499, 990419



## Attachment 2 of FSN GVP-2018-Triton-001

TMD-006 Rev.0

# **Closing Confirmation Sheet**

1
TODCON

RI OCT Triton, DRI OCT Triton plus Software, Ver.1.1.4			
Customer name	Installation date	/ / /	
Address	Agency/Supplier	Business office	
TEL() -	The body model:	The body S/N:	

# ⊕ Version Up check procedure of a software

	Procedure item	Check point	PASS	FALL
1	It be Ver1.1.3 in front of Version Up.  (Select "information" from the "SETUP" menu.)			
	Basic Serial No Region Code System 1.1.3 OCT Capture Count Fundus Capture Count	It's confirmed that it's a repair target.		
2	Version Up, error confirmation	An error message don't be indicated.		
3	Version behind Version Up be Ver.1.1.4.  (Select "information" from the "SETUP" menu.)  Basic Serial No Region Code System 1.1.4  OCT Capture Count Fundus Capture Count	Make sure that the version information is as follows.  System 1.1.4	0	
4	Checking existing data	Check existing data by the tool software "PowerSaveLRChecker". If wrong data exist make necessary correction.  Nuber of checked images  Hours taken for the check		

Comment			

Name	Signature	Initials	Date	
TESTING PERFORMED BY				
CUSTOMER				