

URGENT: Medical Device Field Safety Notice

IMPORTANT INFORMATION

To: Distributors / Resellers / Hospital Professionals

Date: 14th of September 2020

REF: CAPA-2020003

Dear Customer,

Bien-Air Surgery SA, manufacturer of OSSEODUO/OSSEOUNO/OSSEODOC/OSSEOSTAP control units, has initiated a **Field Safety Corrective Action** affecting devices that you may have in stock or may have further distributed in your territory. The details of this action are specified below.

This notice needs to be passed onto all those who need to be aware within your organization or any organization where the potentially affected devices have been transferred. Please transfer this notice to other organizations on which this action has an impact.

Please maintain awareness on this notice and resulting action for an appropriate period to ensure effectiveness of the corrective action.

Please report all device-related incidents to the manufacturer, distributor or local representative, and the national Competent Authority if appropriate, as this provides important feedback.

This field safety corrective action is conducted with the full knowledge of Swissmedic and subject to their supervision.

We request that you **read this notice carefully and follow the instructions** given.

The Field Safety Corrective Action is **only applicable to the foot pedals** that are used to drive micromotor in conjunction with the following control units:

- OSSEODUO

- OSSEOUNO

- OSSEODOC

- OSSEOSTAP

PRODUCT

Bien-Air Surgery SA's foot pedals impacted by this Field Safety Corrective action are identifiable as follows:

Product Name: OSSEODUO foot pedal

Product Reference Number (Bien-Air Surgery's catalogue): Ref. 1600517

&

Product Name: OSSEODOC foot pedal (used with OSSEOUNO&OSSEODOC)

Product Reference Number (Bien-Air Surgery's catalogue): **Ref. 1600407**

&

Product Name: OSSEOSTAP control unit

Product Reference Number (Bien-Air Surgery's catalogue): Ref. 1600686

English Field Safety Notice - Foot Pedal Magnet - September 2020 BAS / 14.09.2020 / JGUE Page 1 on 7




	Proc	luct Serial Num	ber:	See below to	able fo	r the impacted	SN		
		16YZZZZ		17YZZZZ		18YZZZZ		19YZZZZ	
	164	1	17A		18A		19A		
	16E		17B		18B		19B		
	160 160		17C 17D		18C 18D		19C 19D		
	166		17E		18E		19E		
	16F		17F	0001 up to	18F	0001 up to		0001 up to	
	160	9999	17G	9999	18G	9999		9999	
	16H	1	17H		18H				
	161		171		181				
	16J 16k		17J		18J 18K				
	16L		17K 17L		18L				
	100	· [<u> </u>		<u> </u>	<u> </u>		<u> </u>
	Wh	ere to find the f			and se]
	On the		bottom		Zoom on the label		bel		
		•							
								240	
		REF 1600407 PX8							
		SN 19D0030 C€							
		0120				0120			
		•							
	This fie	ld safety correc	tive act	ion has been i	nitiate	d because the	re is a	low possibility	that the
		t located inside							
REASON	-	may compromise the device's safety.							
		e of the incrimin		•					
		when acting on the foot pedal and Bien-Air Surgery SA intends to undertake the below actions to mitigate the risk.							v actions
		implementing	and rel	easing this Fig	eld Sat	fety Corrective	Actio	n, Bien-Air Sur	rgery SA
HEALTH		ned a detailed		-		•			
HAZARD		Risk Index w				•		•	
ANALYSIS	implementing this Field Safety Corrective Action, the occurrence probability becomes								
	negligible to assure full safety use of the device. To date, no patient injury has been reported. Bien-Air Surgery SA was able to show that this hazardous situation is mainly linked to high								
	shocks during installation or use of the foot pedal. We therefore ask the users to treat thi						_		
	device with great caution and to avoid shocks.								
INADODTANIT			-			nediate and temporary) and corrective (long			
IMPORTANT INFORMATION	(erm) a	term) actions to prevent the magnet coming off:						ealthcare	
		- Curative actions , as described below, must be implemented by a healthcare professional in order to ensure device safety until the corrective actions are							
	implemented.								
	- Corrective actions will follow shortly after the release of this Field Safety Notice. Bien-								
	Air Surgery SA will provide detailed information in a separate document. The expected corrective actions availability is December 2020, at the latest.								
		corrective action	ns ava	nability is Dece	mper	∠u∠u, at the lat	est.		



Please find below the procedure to follow for the curative actions:

- Inspect your inventory for the product numbers/serial numbers above.
- Quarantine any of the affected products until performing the following actions
- Open the foot pedal rocker to have access to the incriminated magnet by pulling the black part





The magnet is fully off

Carefully inspect the position of the magnet using the below illustration. When slightly pressing on the magnet, it shouldn't move.

CURATIVE ACTIONS

The



magnet





The magnet is partially off or

moves when pressing

Continue with action N°5

well

is



KEEP THE FOOT PEDAL IN QUARANTINE (DO NOT USE IT ANYMORE), contact your local representative for Bien-Air Surgery products who will organize the repair

Carefully clean the plastic area around the magnet with a disinfectant wipe (e.g. alcoholic solution) and a swab to correctly clean the corners





Make sure the surface is clean and dry before applying an adhesive tape (e.g. Scotch®, width between 10-15mm, length between 55-60mm) as described below









Adhesive tape correctly applied



Too short

Too width, not correctly applied





THE FOLLOWING ACTIONS MUST BE PERFORMED BEFORE EACH SURGERY

7) Carefully inspect that the adhesive tape is correctly holding the magnet and that the magnet is still correctly positioned. If needed, remove the tape and restart the process from step 4.

The adhesive tape is correctly applied and the magnet correctly positioned

The adhesive tape is correctly applied but the magnet NOT correctly positioned





Continue with action N°8

KEEP THE FOOT PEDAL IN QUARANTINE (DO NOT USE IT ANYMORE), contact your local representative for Bien-Air Surgery products who will organize the repair

- 8) Close the foot pedal rocker, connect the foot pedal cable to the control unit and switch it ON
- Proceed with the following tests before performing the surgery
 - Select one motor (BASCH, 80K, NANO, RAPIDO) or one handpiece (S120,



1							
	OSSEOSTAP, PERFO) depending on your needs						
	 b. Hold the motor or handpiece carefully in your hand 						
	c. Press the foot pedal until its maximal position and release it						
	d. The motor or handpiece should run and then stop immediately. If it is not the						
	case, you must KEEP THE FOOT PEDAL IN QUARANTINE (DO NOT USE IT						
	ANYMORE), contact your local representative for Bien-Air Surgery products						
	who will organize the repair. If the motor or handpiece is stopped						
	immediately, the system is ready for the surgery						
	Bien-Air Surgery SA regrets the inconvenience caused to you by this action and would like to						
	thank you for your co-operation in this matter.						
	We are kindly requesting you to acknowledge this notification by sending us back the below						
	reply form as soon as possible.						
OTHER	It is important that your organisation takes the actions detailed in the Field Safety Notice and						
INFORMATION	confirms that you have received the Field Safety Notice. Your organisation's reply is the						
	evidence Bien-Air Surgery SA needs to monitor the progress of the corrective actions.						
	Should you require any further information or have any queries on the matter please do not						
	hesitate to contact Bien-Air Surgery SA's at:						
	- qa.bienair.surgery@bienair.com						
	- +41 32 953 35 35.						

On and for the behalf of Bien-Air Surgery:

Arnaud Billot Regulatory Affairs Manager Jonas Guerdat CTO Juan Elices CEO



FIELD SAFETY CORRECTIVE ACTION REPLY FORM

REF: CAPA-2020003

I hereby certify that I have received, read and understood the Field Safety Notice.

The information and required actions requested by the Field Safety Notice have been brought to the attention of all relevant users and the actions have been **executed in accordance with Bien-Air Surgery SA's instructions** provided in it.

COMPANY NAME & ADDRESS:	
CONTACT NAME:	
CONTACT POSITION:	
CONTACT PHONE NUMBER:	
CONTACT E-MAIL:	
SIGNATURE:	
DATE:	

The devices in the table below have been identified in our premises and the following actions have been undertaken.

Product Name	Reference number	Serial number	LOCATION (own stock or customer name & address)	UNDERTAKEN ACTIONS



Please complete and return this form to:

Bien-Air Surgery SA

Regulatory Affairs Department Rue de l'Ouest 2b CH-2340 Le Noirmont Switzerland

Fax: +41 32 953 35 37

e-mail: qa.bienair.surgery@bienair.com