

URGENT FIELD SAFETY NOTICE: RA2021-2744351

ACTION REQUIRED

July, 2021

Identification of the Affected Product:

Restoris® MCK Femoral Trial and Restoris® MCK Patellofemoral Trial

Refer to Attachment: PFA 2744351 Restoris® MCK Femoral Trial and Restoris® MCK Patellofemoral Trial for affected catalog and lot numbers.

Dear Customer,

Stryker has initiated a voluntary, lot number specific recall for:

- Restoris® MCK Femoral Trial, sizes 1 through 8 and 11 through 18 (LM/RL and RM/LL), of 16 catalog numbers (170501- 170508) and (170511–170518).
- Restoris® MCK Patellofemoral Trial, sizes 2 through 8 and 12 through 18 (Left and Right), of 14 catalog numbers (170402 170408) and (170412 170418).

The intent of this letter is to list hazards and harms potentially associated with the referenced products listed in Attachment: PFA 2744351 and list any risk mitigation factors.

Description of issue:

Stryker has discovered that there is a potential that the threads on the Femoral Trial Slaphammer may not engage with the threads of the Restoris® MCK Femoral Trial(s) and/or Restoris® MCK Patellofemoral Trial(s), (collectively, "Trial(s)"), preventing the extraction of such Trials using the slaphammer after use. This is due to an undersized diameter of the non-threaded portion of the Trial's extraction hole, which may prevent the Femoral Trial Slaphammer from completely engaging.


As a result of this discrepancy, customers are instructed to confirm that the threads of Restoris® MCK Femoral Trial(s) and Restoris® MCK Patellofemoral Trial(s) are able to fully engage with their Femoral Trial Slaphammer(s) at the site prior to use. Quarantine and discontinue use of the Trials identified in the affected product list that do not fully engage with the Femoral Trial Slaphammer and return the devices back to Stryker.

The Restoris® MCK Femoral Trial(s) and Restoris® MCK Patellofemoral Trial(s) continue to meet their intended use of assessing the final fit and function of the femoral and patellofemoral implant prior to implantation.

Figure 1 below displays a Femoral Trial Slaphammer engaging with a Trial (conforming extraction hole) in the image at left, and a Femoral Trial Slaphammer that does not engage with the Trial in the image at right.

Figure 1	-
----------	---







Stryker is aware of complaints associated with the issue. There have been no reports of serious injuries due to the failure mode associated with this recall.

Potential Hazards:

• Failure to assemble the Restoris® MCK Femoral and Restoris® MCK Patellofemoral Trial with the Femoral Trial Slaphammer.

Potential Harms:

• There are no harms associated with the potential hazard identified above.

Risk Mitigations:

If the surgeon is unable to assemble the Femoral Trial Slaphammer with a Restoris® MCK Femoral or Patellofemoral Trial(s) for extraction, the surgeon can use an alternative surgical instrument (or similar device) to remove the Trial(s).

Recommendations for patients already treated with an affected device:

Patients treated with an affected product should continue to be followed per the normal protocol established by his or her surgeon(s). There are no recommended changes to the frequency of the standard follow-up care protocol.

It should be noted that the failure of the insert to fully seat, may not be evident on x-ray unless the insert has dislodged.

Required customer actions:

Our records indicate that you have received at least one of the subject devices and you are therefore affected by this action.

We request that you read this notice carefully and complete the following actions:

- 1. Immediately check your internal inventory and quarantine all subject devices pending return to Stryker.
- 2. Circulate this Field Safety Notice internally to all interested/affected parties.



- 3. Maintain awareness of this notice internally until all required actions have been completed within your facility.
- 4. Inspect all Restoris® MCK Femoral Trial(s) and Restoris® MCK Patellofemoral Trial(s) to ensure that its threaded extraction hole(s) engages with any available Femoral Trial Slaphammers at your site.
- 5. <u>Discontinue use</u> of the recalled trial devices identified in Attachment PFA 268287, which do not engage with your Femoral Trial Slaphammer(s) and return the Restoris® MCK Femoral Trial(s) and Restoris® MCK Patellofemoral Trial(s) devices to Stryker.
- 6. **Continue to use** the Restoris® MCK Femoral Trial(s) and Restoris® MCK Patellofemoral Trial(s)if the threads fully engage with the threads on the Femoral Trial Slaphammer.
- 7. Inform Stryker if any of the subject devices have been distributed to other organizations.
 - a. Please provide contact details so that Stryker can inform the recipients appropriately.
 - b. If you are a Distributor, note that you are responsible for notifying your affected customers.
- 8. Please inform Stryker of any adverse events concerning the use of the subject devices.
 - a. Please comply with any local laws or regulations concerning the notification of adverse events to your National Competent Authority.
- 9. Complete the attached customer response form. It may be that you no longer have any physical inventory on site. Completing this form will allow us to update our records and will also negate the need for us to send any further unnecessary communications on this matter. Therefore, please complete even if you no longer have any of the subject devices in your physical inventory.
- 10. Return the completed form to your nominated Stryker Representative (indicated below) for this PFA
 - a. On receipt of the form, a Stryker Representative will contact you to organize any applicable ongoing actions.

We request that you respond to this notice within 7 calendar days from the date of receipt.

Your designated contact person for this action is given below. Should you have any queries concerning this matter please do not hesitate to contact them directly.

Name:

Position:

E-mail:

Phone:

In line with the recommendations of the Meddev Vigilance Guidance document Ref.2.12-1, we can confirm that this FSCA has been notified appropriately to the National Competent Authority for your country.



On behalf of Stryker we thank you sincerely for your help and regret any inconvenience that may be caused. We would like to reassure you that Stryker is committed to ensuring that only conforming devices, meeting our high internal quality standards and your expectations, remain on the market.

Sincerely,

Stryker URGENT FIELD SAFETY NOTICE: RA2021-2744351 **BUSINESS REPLY FORM**

July 2021				
Product Name:	Restoris ®MCK Femoral Tria	l and Restoris ®M	ICK Patellofemoral Tria	l
Catalog and Lot#:	Refer to Attachment: PFA 27-	14351		
	t Medical Device Recall letter ove referenced affected produc		ed July 7, 2021 informat	ion on the
I have inspected the Res within my inventory.	toris ®MCK Femoral Trial an	d/ or the Restori	is ®MCK Patellofemor	al Trial produc
Hospital/Agent/Risk Rep	or Stryker Branch Rep Name			
ospital/Agent/Risk Rep or Stryker Branch Rep Name ospital or Stryker Branch Name			Date	-
Hospital or Stryker Brancl	h Address/ City/State/ Postal C	ode		_
Hospital/Agent/Risk Rep (Signature)	or Stryker Branch Rep			
	S FORM WITHIN 5 BUSINESS I	DAYS AND RETUR	RN IT BY USING THE E	MAIL OR FAX
Fax: xxxx or email to xxxx				



Attachment: PFA 2744351 Restoris ®MCK Femoral Trial and Restoris® MCK Patellofemoral Trial

Catalog #	GTIN#	Lot#												
170402	848486003319	1N3G	170415	848486003425	1QGP	170501	848486003463	18QP	170507	848486003524	12HN	170515	848486003586	16W3
170402		1BM0	170415		1L8N	170502	848486003470	11HG	170507		12HM	170515		16W4
170402		18QN	170415		1CYD	170502		11HH	170507		15XY	170515		16W1
170402		18QM	170415		14X9	170502		11HE	170507		15Y0	170515		16W2
170402		182Y	170415		13BJ	170502		1GX7	170507		15Y1	170515		1EAV
170402		1830	170416	848486003432	2JP4	170502		22PG	170507		1N32	170515		1GLM
170403	848486003326	2JNE	170416		1WWJ	170502		23L4	170507		1N31	170515		1HNW
170403		1WWG	170416		1WWL	170502		23L5	170507		1N30	170515		1HNV
170403		15XV	170416		1GX2	170502		22PE	170507		1NN6	170515		38P8
170403		11HN	170416		1GX3	170503	848486003487	14X5	170507		1NN5	170516	848486003593	14BP
170404	848486003333	2JNM	170417	848486003449	20V9	170503		16W8	170507		1NN8	170516		17CB
170404		1WWH	170417		1V0E	170503		182X	170508	848486003531	11AC	170516		1AE1
170405	848486003340	1Q0V	170417		1M26	170503		1G3X	170508		16VN	170516		1B0A
170405		1BLM	170417		1CYB	170503		1G3W	170508		1CY9	170516		1AE2
170405		1BLL	170417		1ADJ	170503		2R0D	170508		1M21	170516		1B09
170405		17C3	170418	848486003456	32E3	170503		2JPV	170508		1QGN	170516		1CYA
170405		17C4	170418		2Q3G	170503		2R0E	170508		1WWM	170516		1MGD
170405		11HW	170418		2Q3H	170503		38J6	170508		24X3	170516		1MGC
170406	848486003357	17C9	170418		2DPG	170503		38J8	170508		288E	170516		1MGB
170407	848486003364	1Q0Q	170418		1YW7	170503		38J7	170508		288G	170516		22PD
170407		1Q0R	170418		1BLR	170504	848486003494	17BX	170508		2XP1	170517	848486003609	12HD
170408	848486003371	2Q3D	170418		1ADM	170504		1R5X	170508		2XNX	170517		15Y2
170408		2JPA	170418		17CA	170504		1QGR	170511	848486003548	1PAP	170517		15Y3
170408		2D2V				170504		1R5W	170511		1NNN	170517		19A7
170408		1VQE				170505	848486003500	11AG	170512	848486003555	11A7	170517		19A8
170408		1Q0W				170505		11AE	170512		11J3	170517		1C1Q
170408		1HNG				170505		11AD	170512		11J2	170517		1GLB
170408		199M				170505		1835	170512		20RV	170517		1GLC
170408		1B07				170505		19A0	170512		20RR	170517		2A2H
170412	848486003395	1W74				170505		1968	170513	848486003562	1V09	170517		2A2J
170412		1CYC				170505		1AE7	170513		1V0A	170517		2JQC
170412		15XN				170505		1CCQ	170513		227B	170518	848486003616	1EAX
170412		11HX				170505		1CCN	170513		20V6	170518		1EBO
170412		11HY				170505		1CCP	170514	848486003579	11A1	170518		1EAY
170413	848486003401	1MG3				170506	848486003517	14BM	170514		1964	170518		1MG8
170413		1G40				170506		18R5	170514		1963	170518		1M20
170413		1GLN				170506		1837	170514		1L8Q	170518		1L8D
170414	848486003418	246P				170506		18R4	170514		1L8P	170518		1MG7
						170506		1GXJ	170514		21H2	170518		1MG6
						170506		1GXL	170514		21H3	170518		1M1Y
						170506		1JRL	170514		23L3			
									170514		23L2			