

Date: 17/09/2021

**Urgent Field Safety Notice**

TETANUS VIRCLIA<sup>®</sup> IgG MONOTEST

**For attention of:** Distributor/Final user

<b>Manufacturer Contact details:</b>
<b><u>Vircell, S.L.</u></b> Parque Tecnológico de la Salud, Avicena 8, 18016, Granada, Spain
<b>Local contact details:</b>
Local distributor

**Urgent Field Safety Notice (FSN)**

TETANUS VIRCLIA<sup>®</sup> IgG MONOTEST

**Risk addressed by FSN**

<b>1.-Information on Affected Devices</b>	
1	1.-Device Type Indirect chemiluminescent immunoassay (CLIA) to test quantitatively IgG antibodies against <i>Clostridium tetani</i> toxin in human serum/plasma.
1	2.-Commercial name TETANUS VIRCLIA <sup>®</sup> IgG MONOTEST
1	3.-Unique Device Identifier (UDI-DI) 8436040326640
1	4.-Primary clinical purpose of device For in vitro diagnosis.
1	5.-Device reference VCM004
1	6.-Affected serial or lot number range 21C004002
1	7.-Associated devices This device is used in combination with an automated processor: VIRCLIA <sup>®</sup> LOTUS and VIRCLIA <sup>®</sup> (TB).

<b>2.-Reason for Field Safety Corrective Action (FSCA)</b>	
2	1.-Description of the product problem A labelling error has been detected in lot 21C004002 of the reference TETANUS VIRCLIA <sup>®</sup> IgG MONOTEST (VCM004). This error was detected due to a claim from the Spanish distributor. The product labelling includes a bar code with the data for the master curve required for the use of the kit in combination with the automated processors (VIRCLIA <sup>®</sup> LOTUS and VIRCLIA <sup>®</sup> (TB)). The labelling error consists of barr codes included in the label, in order to allow the use of the kits in combination with automated processors, being wrong. Results from the final quality control of the device show that the product is correct and fulfils specifications. This error solely affects labelling.
2	2.-Hazard giving rise to the FSCA This error might generate false negatives when the kit is used for quantitative determination in the VIRCLIA <sup>®</sup> (TB) automated processor. Determinations performed using VIRCLIA <sup>®</sup> LOTUS are not affected.
2	3.-Probability of problem arising Probability of problem arising is low because this error only arises when determinations are performed in the VIRCLIA <sup>®</sup> (TB) automated processor. Additionally, this error is easy to detect, as general population is vaccinated against tetanus and

	getting a negative result is highly unlikely. In the case that the error is not detected false negative results might be obtained when using the VIRCLIA® (TB) automated processor.
2	<p>4.-Predicted risk to patient/users</p> <p>Risk is low because the probability of detecting the error is very high and, in that case, the result is not delivered.</p> <p>On the other hand, even in the case that the error is not detected and a false negative was obtained, method limitations in the instructions for use indicate that “the results of samples should be used in conjunction with clinical evaluation and other diagnostic procedures. A definitive diagnosis should be made by direct diagnostic techniques”. Additionally, the insert indicates that “this test has been only validated as a screening assay; follow local guidelines for the management of tetanus-prone wounds regarding the convenience of booster vaccination and tetanus immunoglobulin administration”. Finally, it should be taken into account that patient health will not be affected if vaccinated after getting a false negative.</p>

<b>3.-Type of Action to mitigate the risk</b>	
3	<p>1.-Action to be taken by the user</p> <p><input type="checkbox"/> Identify device   <input type="checkbox"/> Quarantine device   <input checked="" type="checkbox"/> Return device   <input type="checkbox"/> Destroy device</p> <p><input type="checkbox"/> On-site device modification/inspection</p> <p><input type="checkbox"/> Follow patient management recommendations</p> <p><input type="checkbox"/> Take note of amendment/reinforcement of instructions for use (IFU)</p> <p><input type="checkbox"/> Other                                      <input type="checkbox"/> None</p>
3	<p>2.-Is customer reply required?                                      Kits return</p>
3	<p>3.-Action being taken by the manufacturer</p> <p><input checked="" type="checkbox"/> Product removal                                      <input type="checkbox"/> On-site device modification/inspection</p> <p><input type="checkbox"/> Software upgrade                                      <input type="checkbox"/> IFU or labelling change</p> <p><input type="checkbox"/> Other    <input type="checkbox"/> None</p>

<b>4.-General information</b>	
4	1.-FSN Type                                      New
4	2.- Further advice or information already expected in follow-up FSN?                                      No
4	3.-Manufacturer information
	a. Company name                                      Vircell,s.l.
	b. Address                                      Parque Tecnológico de la Salud, Avicena 8, 18016, Granada, Spain
	c. Website address                                      www.vircell.com
4	4.-The Competent (Regulatory) Authority of your country has been informed about this communication to customers                                      Yes
4	5.-List of Attachment/appendices                                      Distributor Verification form
4	6.-Name/Signature                                      Arantxa Cortés Ruiz

**Transmission of this Field Safety Notice**

This notice needs to be passed on all those who need to be aware within your organisation or to any organisation where the potentially affected devices have been transferred.

Please transfer this notice to other organisations on which this action has an impact.

Please maintain awareness on this notice and resulting action for an appropriate period to ensure effectiveness of the corrective action.

Please report all device-related incidents to the manufacturer, distributor or local representative, and the national Competent Authority if appropriate, as this provides important feedback.