

Urgent Field Safety Notice (Removal) Cordis[®] POWERFLEX[®] PRO PTA Dilatation Catheter

Catalog Number	Lot Number
4400322X	82144115
4400602S	82144141
4400515X	82144947
4400308S	82148810
4400508S	82148811

September 06, 2018

Dear Valued Customer,

The purpose of this communication is to inform you Cordis is recalling (removing) five (5) lots of Cordis[®] POWERFLEX[®] PRO Percutaneous Transluminal Angioplasty (PTA) Dilatation Catheter product.

Recall Overview:	Cordis has determined that five lots of POWERFLEX® PRO PTA Dilatation Catheters have not met an internal manufacturing specification for shaft burst strength, though it meets the label claim (18 ATM).
	A shaft leakage/burst that occurs during balloon inflation would likely create an inability to inflate or maintain pressure of the balloon component. The user may experience inflation difficulty/deflation difficulty of the balloon component. The most likely occurrence would result in a procedural delay, however damage to healthy intima, vessel spasm, ischemia, or additional intervention could result, but only occasionally and/or under unusual circumstances.
	There is no safety concern for patients that are treated successfully using product from these lots.
	Cordis has not received any complaints related to POWERFLEX® PRO that are related to shaft burst or leakage.

Details on	Product involved			
Affected Devices,	• Five (5) lots are	affected:		
to assist in	Catalog Number	Lot Number	Balloon Diameter	Balloon Length
identification of	4400322X	82144115	3mm	22cm
the product	4400602S	82144141	6mm	2cm
involved:	4400515X	82144947	5mm	15cm
	4400308S	82148810	3mm	8cm
	4400508S	82148811	5mm	8cm
	femoral, ilio-femoral, treatment of obstruct fistulae. The device i self-expanding stent	popliteal, infra poplit tive lesions of native is also indicated for p s in the peripheral va	or synthetic arteriove ostdilation of balloon	s and for the nous dialysis -expandable and

Details on Affected Devices,	Identification (Continued) Example labeling:
to assist in identification of the product involved (Continued):	Ø3 mm X 8 cm Ø3 mm X 8 cm Ø3 mm X 8 cm Ø3 mm X 8 cm
	80 cm 5F 15 mm 15 mm 03 mm 11 3.16 1 3 3.16 15 3.16 1 3 3.16 15 3.16 1 3 3.16 15 3.26 1 3 3.16 15 3.26 1 3 3.16 15 3.26 1 3 3.16 15 3.26 1 3 3.16 15 3.26 1 3 3.16 15 3.26 1 3 3.16 15 3.26 1 3 3.16 15 3.26 1 3 3.16 15 3.26 1 3 3.16 15 3.26 1 3 3.16 15 3.26 1 3 3.16 16 3.26 1 3 3.16 16 3.26 1 3 3.16 16 3.26 1 3 3.16 16 3.26 1 3 3.16 16 3.26 1 3 3.16 16 3.26 1 3 3.16 16 3.26 1 3 3.16 16 3.26 1 3 3.16 16 3.26 1 3 3.16 16 3.26 1 3 3.16 16 3.26 1 3 3.16 16 3.26 1 3 3.16 16 3.26 1 3 3.16 16 3.26 1 3 3.16 16 3.26

Why you are	You are receiving this letter because our records indicate that you have
being contacted:	purchased the POWERFLEX [®] PRO lot numbers indicated in this letter.
Actions requested	1) Read this Field Safety Notice (Removal) letter.
on your part:	
	2) Immediately check your inventory to confirm whether you have any units from the affected lots in your possession. Identify and set aside any units from the affected lots in a manner that ensures the affected product will not be used. Check all storage and usage locations.
	3) Review, complete, sign and return the enclosed Acknowledgement Form in accordance with the directions on the form.
	4) Return all affected product to the Cardinal Health distribution center. Please contact your local sales representative to facilitate return of the affected product, if necessary. Your sales representative will inform you of the product replacement or credit options.
	5) Share this letter with others in your facility who need to be made aware of this recall.
	6) Please contact any other facility who may have received the affected units of POWERFLEX [®] PRO product from your facility. If any units of the affected lots are found to be at the other facility, please arrange the return of the units.
	7) Maintain awareness of this notice until all affected product has been returned to Cordis.
	8) Keep a copy of this notice with the affected product.

Description of the problem: What is the issue? Cordis became aware that the product may not meet the shaft subassembly burst strength specification. Why are we recalling this product? A shaft leakage/burst that occurs during balloon inflation would likely create an inability to inflate or maintain pressure of the balloon component. Additionally, the user may experience inflation difficulty/deflation difficulty of the balloon component. The most likely occurrence would result in a procedural delay, however damage to healthy intima, vessel spasm, ischemia, or additional intervention courted.
subassembly burst strength specification. Why are we recalling this product? A shaft leakage/burst that occurs during balloon inflation would likely create an inability to inflate or maintain pressure of the balloon component. Additionally, the user may experience inflation difficulty/deflation difficulty of the balloon component. The most likely occurrence would result in a procedural delay, however damage to
Why are we recalling this product? A shaft leakage/burst that occurs during balloon inflation would likely create an inability to inflate or maintain pressure of the balloon component. Additionally, the user may experience inflation difficulty/deflation difficulty of the balloon component. The most likely occurrence would result in a procedural delay, however damage to
Why are we recalling this product? A shaft leakage/burst that occurs during balloon inflation would likely create an inability to inflate or maintain pressure of the balloon component. Additionally, the user may experience inflation difficulty/deflation difficulty of the balloon component. The most likely occurrence would result in a procedural delay, however damage to
A shaft leakage/burst that occurs during balloon inflation would likely create an inability to inflate or maintain pressure of the balloon component. Additionally, the user may experience inflation difficulty/deflation difficulty of the balloon component. The most likely occurrence would result in a procedural delay, however damage to
A shaft leakage/burst that occurs during balloon inflation would likely create an inability to inflate or maintain pressure of the balloon component. Additionally, the user may experience inflation difficulty/deflation difficulty of the balloon component. The most likely occurrence would result in a procedural delay, however damage to
create an inability to inflate or maintain pressure of the balloon component. Additionally, the user may experience inflation difficulty/deflation difficulty of the balloon component. The most likely occurrence would result in a procedural delay, however damage to
component. Additionally, the user may experience inflation difficulty/deflation difficulty of the balloon component. The most likely occurrence would result in a procedural delay, however damage to
difficulty/deflation difficulty of the balloon component. The most likely occurrence would result in a procedural delay, however damage to
occurrence would result in a procedural delay, however damage to
occurrence would result in a procedural delay, however damage to
result, but only occasionally and/or under unusual circumstances.
There is no safety concern for patients that are treated successfully using product from these lots.
What other actions is Cordis taking?
Cordis has performed a root cause investigation and taken immediate
corrective action. Cordis has not identified any other lots that may be
affected. In keeping with our commitment to provide customers with
quality products, Cordis has voluntarily decided to recall these five (5)
lots.

Available Assistance:	If you have any questions regarding this recall, please contact your local sales representative or local sales office.
Assistance.	

Additional Information:	Regulatory Notification
	The applicable regulatory agencies and notified body are being notified that Cordis is voluntarily taking this action.

We apologize for any inconvenience this communication may cause. We know that you place high value in our products and we appreciate your cooperation in this matter. Cordis is committed to maintaining your confidence in the safety and quality of the products that Cordis supplies.

Respectfully yours,

Abet

Miguel Ávila Vice President, Global Quality and Regulatory Compliance Cordis Corporation