

**Field Safety Notice (FSN)  
Pulla StretchLift  
Improving safety through retrofitting**

Dear customer,


an incident in which improper use was responsible for the fact that the control button was unintentionally pressed and pulla was unintentionally started, prompts us to carry out this (FSCA).

product problem:  
affected devices:

unintentional actuation  
pulla StretchLift  
Article-Nr. 8266001  
Serial numbers 0001 – 3738  
Attaching a deflector plate  
Article-Nr. 8101617

corrective action required:

**Corrective actions**  
Attaching a deflector plate.  
This corrective action has to be taken.



## Affected customers

According to our records, you have purchased one or more devices from us to which this applies. Attached you will find a list with the serial number/s and the date of purchase of the device/s that we have delivered to you.

At the same time, we will send you the corresponding number of deflector plates with screws, which you then have to attach to the devices. To confirm the retrofitting, please use the attached appendix.

If a device is no longer with you, please pass this letter on to the subsequent owner / new owner.

It is important that you send the completed response form back to us as confirmation so that we can monitor corrective action.

Thank you very much for your support in advance.

e-Mail fsca@aacurat.de  
Fax: +49 7361 921 921  
Post: aacurat GmbH  
Gottlieb-Daimler-Str. 9  
73460 Hüttlingen  
GERMANY

## Reply Form

### Fields Safety Corrective Action (FSCA)

pulla StretchLift, Article-Nr. 8266001

Customer number: \_\_\_\_\_

Customer: \_\_\_\_\_

Address: \_\_\_\_\_

\_\_\_\_\_

pulla StretchLift, Article-Nr. 8266001

Serial number	Delivery date	Date	Name	Signature	Deflector plate attached	Deflector plate not attached	Reason

Date: \_\_\_\_\_

Name: \_\_\_\_\_

Signature \_\_\_\_\_