medartis®

Medartis AG | Hochbergerstrasse 60E | CH-4057 Basel

Xxxxxxxxxx Customer Adress and Contact xxxxxxxxxxxxxxxxxxx

| Place/Date: Basel, 02.01.2020 | Reference: Urgent Field Safety Notice

URGENT: Field Safety Notice

Dear Sir or Madam,

On December 19th, Medartis AG has initiated a lot specific product Field Safety Corrective Action (FSCA) for the 2.5 Trilock Screw 14mm, HD7 (A-5750-14/1S).

Product Recall:	2.5 Trilock Screw 14mm, HD7
Date	19.12.2019
Part Number	A-5750-14/1S Lot 17169656, 18190766, 19194557, 19200335 Number
FSCA identifier	FSCA-2019-001
Type of Action	Field Safety Corrective Action: Product Return to supplier (Medartis AG)
Description of the Problem	Medartis discovered an error on the label of the A-5750.14/1S screws: the mention "not for clinical use" is visible on the label. APTUS QTY: 1 Material: TARkoy medartis (1) 18190766 2.5 TriLock Screw 14mm, HD7 2.5 Tr
Advise on	➤ Please kindly quarantine and return the affected A-5750.14/1S screws

2/2

Actions to be taken	to Medartis.
to be taken	Please kindly fill in and return the attached "Customer Acknowledgement Form" (QF41405). to return@medartis.com
	Please kindly forward this notification to all potentially affected divisions in-house.
	Please be aware that the current information sent per email will also be sent per mail to your facility.
	XXXXXXX
Medartis	E-Mail: return@medartis.com
Contact person	Medartis AG
Kontaktperson	Hochbergerstrasse 60E
	4057 Basel

Swissmedic, our responsible National Authority has been notified on this incident. We kindly apologize for all inconveniences this could cause and remain at your complete disposal for further inquiry.

Kind Regards,

Medartis AG