

ekamed[®] GmbH & Co. KG, Im Stadtfelde 43, 31515 Wunstorf

ekamed[®] GmbH & Co. KG
IM STADTFELDE 43
31515 WUNSTORF
TELEFON 05031-70410-0
TELEFAX 05031-70410-30
i n f o @ e k a m e d . d e
Internet: www.ekamed.de

Update ekamove 30° lateral positioning system - IMPORTANT

Dear ...,

all ekamove 30° lateral positioning systems need to be updated.

The reason for that is, it could be possible, that the software-program goes to sleep. In those cases it could be possible that the positioning of the patient is not accurate.

Theoretically it could happen that the pump does not stop inflating air.

With the software 3.54 this case cannot happen anymore.

We ask you to take care of the update of all ekamoves you have got delivered and to inform your customers as soon as possible. Please find attached the list of the delivered ekamoves.

The instructions for the update will follow.

If you have any questions please do not hesitate to contact us.

Best regards
Mit freundlichen Grüßen

your ekamed-team
Ihr ekamed-team